



SERVICE REPORT

Customer: _____ **Date:** January 5, 2016
W.O.: 534152 _____ **Model:** 0 402 736 913
P.O.: _____ **S/N:** 7682618142

Inspection and Tear Down

Disassembled and inspected. Found the full load stop is damaged. All shafts are worn.

Opinion of probable cause of failure

Normal wear.

Repairs made to failed unit(s)

Reassembled with new parts and calibrated to spec.

Technician: _____