



## SERVICE REPORT

**Customer:** \_\_\_\_\_ **Date:** \_\_\_\_\_  
**W.O.:** 535699 **Model:** DBGVC 631 – 11AF (AR26372R)  
**P.O.:** \_\_\_\_\_ **S/N:** 338471

### **Inspection and Tear Down**

---

Pump shows sign of contamination, and metal filings inside, weight retainer Pins have worn out. Worn governor parts and metering parts.  
End plate screw broken. Head and rotor with sticky and worn plungers.

### **Opinion of probable cause of failure**

---

### **Repairs made to failed unit(s)**

---

Repair made to unit, installed new parts and service kit, bench tested and Calibrated within specification.

**Technician:** 120

---