



**INJECTOR SERVICE REPORT**

<b>Customer:</b>		<b>DATE:</b>	
<b>Part Number:</b>	104075-1554	<b>W.O.:</b>	556241
<b>Nozzle Number:</b>		<b>P.O.:</b>	

**Inspection and Tear Down**

SPEC.:	120-150	Test as Received	Test Following Service	
		#1: 100	#1:	150
		#2: 90	#2:	150
		#3: 70	#3:	150
		#4: 105	#4:	150
		#5:	#5:	
		#6:	#6:	
		#7:	#7:	
		#8:	#8:	
		#9:	#9:	
		#10:	#10:	
		#11:	#11:	
		#12:	#12:	

**Repairs Made to Failed Unit(s)**

**Technician:** \_\_\_\_\_