

Customer

GCL INTERNAL

EDMONTON, AB

Tel.:

Fax:

Job number: 556850

Customer number:

Testing agency

GCL Diesel Injection Service

15842-112 Avenue

Edmonton, AB

Tel.: 7804536786

Fax: 7804475854

Operator KHPRKD

WID: 4b 48 30 30 30 30 ba a6 67 (Hex)

Test unitOrder number: **0470506027**

Serial number: 107606

Vehicle: Cummins-Chrysler

Model formula: VR/6/3/75M1600R1000

Date of prod.: 584

Change index: 101

Verification: ---

Pump comparison: OK

Blocking: OK

WarrantyRequested: Yes No

Error number: _____

Recognised: Yes No

Seal: _____

Stamp, Date, Signature**Test equipment**

Test nozzle holder: 1688901035

Nozzle opening pressure: 20.70 + 0.30 MPa (207.00 + 3.00 bar)

Perforated-plate diameter: 0.5 mm

Test pressure line: 1680750093

Overflow valve number: 1467445003

Inlet pressure: 30 kPa ± 5 kPa

Battery voltage: 13.5 V ± 0.1 V

Customer complaint

REPAIR FOR STOCK.

Problem

SCORED HOUSING, ADVANCE PISTON AND SUPPLY LINER. CRACKED DIAPHRAGM.

Remarks

OVERHAUL, CALIBRATE AND BLOCK PUMP TIMING.